BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. : 773 Date : 17/08/2020

1. Customer's Name and Address : K.V. Subba Reddy -
   With Telephone No. 9980915550
2. Well Location : C 3rd Main, 7th Cross, C. Ramaiha Layout
3. Total Well Depth / Drilled in Ft. : 1180 ft -
4. Casing Erected in Ft. : 240 ft -
5. Water Struck at the Depth of : 850 ft -
6. Total Yield (Measuring method "V" North 2.5" / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clear
8. At the Depth of : -
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Executive Engineer ... Sub Division ... 97

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Sunitha-NK AE DIO

Party's Signature

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. 775 Date : 25/08/2020

1. Customer's Name and Address : K.V. Subba Reddy
   With Telephone No. 9980915550
2. Well Location : 2nd 'A' cross, Nanjappa Layout, D.B Sandra
3. Total Well Depth / Drilled in Ft. : 1060 ft
4. Casing Erected in Ft. : 280 ft
5. Water Struck at the Depth of : 910 ft
6. Total Yield (Measuring method "V" North 3" / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear : Clear
8. At the Depth of :
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

ME-10

Executive Engineer
Sub Division
Bangalore-97

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Sureetha. K/R
AE/10

Party's Signature

Manager / ~~Proprietor~~.

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. : 776 Date : 26/08/2020

1. Customer's Name and Address : K.V. Subba Reddy -
   With Telephone No. 9980915550
2. Well Location : 1st Main Road, Ramana Garden, (Info) Mitra Apartments
3. Total Well Depth / Drilled in Ft. : 1150 ft
4. Casing Erected in Ft. : 310 ft
5. Water Struck at the Depth of : 980 ft -
6. Total Yield (Measuring method "V" North 2.5" / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clear
8. At the Depth of : —
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

ME-10 Executive Engineer Zone Division 97

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Suvetha. N.R AE WID

Party's Signature

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. : 772 Date : 14/8/2020

1. Customer's Name and Address : K.V. Subba Reddy –
   With Telephone No. 9980915550 –
2. Well Location : Doddabommasandra, 4th Stage, 1st cross
3. Total Well Depth / Drilled in Ft. : 1150 ft –
4. Casing Erected in Ft. : 260 ft –
5. Water Struck at the Depth of : 860 ft –
6. Total Yield (Measuring method "V" North 3" / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear clear –
8. At the Depth of :
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Party's Signature

Manager / Proprietor

BOREWELL COMPLETION REPORT

VINAYAKA ENTERPRISES

Borewell Drilling Contractors

No. 9, Bhadrappa Layout, Bhadrappa Compound, Near Hebbal, Ring Road, Bangalore - 560 094
Mobile : +91 9342202932 | 9343202932

No. : 774 Date : 20/08/2020

1. Customer's Name and Address : K.V. Subba Reddy –
   With Telephone No. 9980915550 –
2. Well Location : Muthuraya Swamy Layout, Ramchandra pura
3. Total Well Depth / Drilled in Ft. : 1100 ft –
4. Casing Erected in Ft. : 220 ft –
5. Water Struck at the Depth of : 900 ft –
6. Total Yield (Measuring method "V" North 3" – / inches on " V" North)
7. Formation of Soil / Well Water Condition :
   Boulders / Silt / Loose Soil / Clear Clear –
8. At the Depth of : –
9. Recommended to use Jet Pump / Air Compressor / Submersible / Hand Pump

The Borewell was drilled in accordance with the company terms and conditions and handed over to customer in good / satisfied / Party agreed conditions.

Once the well handed over to party, Company is no way responsible for further developments if anything in the well or what so ever.

Party's Signature

Executive Engineer Sub Division 97

I Owner of the Well / (Authorised signatory) fully understood the terms and conditions and the well completion report, I also fully understood the quality and quantity of water from the well duly depend upon the nature / formation of ground water and the drilling agency no way responsible for further occurrence / Changes in the bore with full satisfaction. I hereby endorse my signature.

For VINAYAKA ENTERPRISES

Sunitha. N K AE WID

Party's Signature

Manager / Proprietor

Bhustalimath B M (Basavaraj)
B Sc, B Ed, DIRPM, LL B(Spl), CAIIB, MBA

Consultant in Groundwater investigation & Water Harvesting

REPORT ON GROUNDWATER INVESTIGATION/SURVEY

Ref by BBMP Contact Person: K.V. Subba Reddy

Owner: Byatarayanapura division

Address of the site: Muthuraja Swamy Temple layout, Ramachandrapura.

Purpose of Survey: Agri/Resi/Domestic/Coml/Indl/Public Utility/Buying & Selling of lands/RE

Type: Hydrological survey/ second opinion/ Failed or weak Borewell/ good

Location: (Latitude/longitude): North: ✓ East: ..... (N.A)

Soil: Sandy/Loamy/Clayey/ ✓ Red/ Black/.....

Topography: Clear

Groundwater recharge condition: Excellent/Very good/Moderate/Poor/Very poor/.....

Date of Investigation: Validity: 90 days

Methods adopted: (1)'L' Rods( )(2) Copper wand ( )(3) Coconut ( )(4) Brunton compass( )
(5)'Y' notch ( ) (6) Pendulum/Bob/Chain/Necklace/Wrist watch/Water ball/Mud ball ( )
(7) Geomagnetic flux ( ) (8) Infrasonics ( ) (9) Geobiology( ) (10) Topography/Geomorphology
( ) (11) Vertical Electrical Sounding/Resistivity (VES/VER) ( )(12) Water Detector( )
(13) Water scanner ( ) (14) ..... ( )

Based on above findings/investigations/observations, the following suggestions are made.

Depth to be drilled: About 1000 Mtrs/Ft, Casing Pipe: 200 Mtr/Ft (MS/PVC/Out/In)

Depth to water source/s: About 900 – 1000 Mtr/Ft(stream/aquifer/)

Approx total yield of water: About ____ Inch dia or About ____ Ltrs/Gal(=4.5 L)per hour.

Diameter of the borewell in inches suggested: 4 ½( ) 6( ) 6 ½( ) 7( ) 7 ½( ) 8( ) 10( )

Special instructions: (a) Align the driller on the streamline; (b) perfect 90 degree drilling.

Brief Map/Identification of Point/s: (Paper-top presumed to be north, right side as east)





Disclaimer: The above depths and yield are indicative, based on the findings at the time of investigation. There is no guarantee as to depths and discharge of water, as the results are beyond our control. Jurisdiction: Bangalore city. *(Tips: Yield= 2600 X Square of inches got)*

Please pay/Received Rs.....(Rs. 2,000)towards this groundwater investigation/survey.

Place: Bangalore

Date: 03/08/2020

Bhustalimath B M

Groundwater & Water Harvesting Consultant

Mobiles - 9538909542 & 990-498502 OR 7411008937

#95, TF-1, Adishree Aptt, Nr Krishna temple, DBSandra, Vidyaranyapura Po, Bangalore-560097 (India)
Cell: [redacted]9538909542 Resi; [redacted] Mail: bmbmath@gmail.com & [redacted]

7902 498 502

C - Casing
I - Inner
O - outer
S - Slotted

S - Stream
A - Aquifer

M - Motor (Submersible)/Pump
W - Water level.
P - Pipe (GI/PVC)

Bhustalimath B M (Basavaraj)
B Sc, B Ed, DIRPM, LL B(Spl), CAIIB, MBA

Consultant in Groundwater investigation & Water Harvesting

REPORT ON GROUNDWATER INVESTIGATION/SURVEY

Ref by BBMP Contact: K.V. Subba Reddy Person

Owner: Byatarayanapura Division

Address of the site: Dattakumaraswamy, 4th Stage, 18th Cross

Purpose of Survey: Agri/Resi/Domestic/Coml/Indl/Public Utility/Buying & Selling of lands/RE.

Type: Hydrological survey/ second opinion/ Failed or weak Borewell/ Good

Location: (Latitude/longitude): North: ✓ East: ..... (N.A)

Soil: Sandy/Loamy/Clayey/ ✓ Red/ Black/ ✓

Topography: Clear

Groundwater recharge condition: Excellent/Very good/Moderate/Poor/Very poor/.....

Date of Investigation: Validity: 98 days

Methods adopted: (1)'L' Rods( )(2) Copper wand ( )(3) Coconut ( )(4) Brunton compass( )
(5)'Y' notch ( ) (6) Pendulum/Bob/Chain/Necklace/Wrist watch/Water ball/Mud ball ( )
(7) Geomagnetic flux ( ) (8) Infrasonics ( ) (9) Geobiology( ) (10) Topography/Geomorphology
( ) (11) Vertical Electrical Sounding/Resistivity (VES/VER) ( )(12) Water Detector( )
(13) Water scanner ( ) (14) ..... ( )

Based on above findings/investigations/observations, the following suggestions are made.

Depth to be drilled: About 1100 Mtrs/Ft, Casing Pipe: 250 Mtr/Ft (MS/PVC/Out/In)

Depth to water source/s: About 800 - 1000 Mtr/Ft(stream/aquifer/)

Approx total yield of water: About ____ Inch dia or About ____ Ltrs/Gal(=4.5 L)per hour.

Diameter of the borewell in inches suggested: 4 ½( ) 6( ) 6 ½( ) 7( ) 7 ½( ) 8( ) 10( )

Special instructions: (a) Align the driller on the streamline; (b) perfect 90 degree drilling.

Brief Map/Identification of Point/s: (Paper-top presumed to be north, right side as east)

N
E



Disclaimer: The above depths and yield are indicative, based on the findings at the time of investigation. There is no guarantee as to depths and discharge of water, as the results are beyond our control. Jurisdiction: Bangalore city. *(Tips: Yield= 2600 X Square of inches got)*

Please pay/Received Rs.....(Rs. 2,000)towards this groundwater investigation/survey.

Place: Bangalore
Date: 3/08/2020

Bhustalimath B M
Groundwater & Water Harvesting Consultant

Mobiles - 9538909542 & 9902498502 OR 7411008937

#95, TF-1, Adishree Aptt, Nr Krishna temple, DBSandra, Vidyaranyapura Po, Bangalore-560097 (India)
Cell: [redacted]9538909542 Resi: [redacted] Mail: bmbmath@gmail.com & [redacted]

9902 498 502
C - Casing
I - Inner
O - outer
S - Slotted

S - Stream
A - Aquifer

M - Motor (Submersible)/ Pump.
W - Water level.
P - Pipe (GI/PVC)

Bhustalimath B M (Basavaraj)
B Sc, B Ed, DIRPM, LL B(Spl), CAIIB, MBA

Consultant in Groundwater investigation & Water Harvesting

REPORT ON GROUNDWATER INVESTIGATION/SURVEY

Ref by BBMP Contact: K.V. Subba Reddy (Person)

Owner: Byatarayanapura Divisn

Address of the site: 1st main road, Ramanna garden, Mitra Apartments, Doddabommasandra

Purpose of Survey: Agri/Resi/Domestic/Coml/Indl/Public Utility/Buying & Selling of lands/RE.

Type: Hydrological survey/ second opinion/ Failed or weak Borewell/ good

Location: (Latitude/longitude): North: ..... East: ..... (N.A)

Soil: Sandy/Loamy/Clayey/ ~~Red~~/ Red/ Black/ ~~Black~~

Topography: clear

Groundwater recharge condition: Excellent/Very good/Moderate/Poor/Very poor/.....

Date of Investigation: Validity: 90 days

Methods adopted: (1)'L' Rods( )(2) Copper wand ( )(3) Coconut ( )(4) Brunton compass( )
(5)'Y' notch ( ) (6) Pendulum/Bob/Chain/Necklace/Wrist watch/Water ball/Mud ball ( )
(7) Geomagnetic flux ( ) (8) Infrasonics ( ) (9) Geobiology( ) (10) Topography/Geomorphology
( ) (11) Vertical Electrical Sounding/Resistivity (VES/VER) ( )(12) Water Detector( )
(13) Water scanner ( ) (14) ..... ( )

Based on above findings/investigations/observations, the following suggestions are made.

Depth to be drilled: About 1100 Mtrs/Ft, Casing Pipe: 270 Mtr/Ft (MS/PVC/Out/In)

Depth to water source/s: About 960 – 1200 Mtr/Ft(stream/aquifer/..)

Approx total yield of water: About ____ Inch dia or About _____ Ltrs/Gal(=4.5 L)per hour.

Diameter of the borewell in inches suggested: 4 ½( ) 6( ) 6 ¼( ) 7( ) 7 ½( ) 8( ) 10( )

Special instructions: (a) Align the driller on the streamline; (b) perfect 90 degree drilling.

Brief Map/Identification of Point/s: (Paper-top presumed to be north, right side as east)



Disclaimer: The above depths and yield are indicative, based on the findings at the time of investigation. There is no guarantee as to depths and discharge of water, as the results are beyond our control. Jurisdiction: Bangalore city. *(Tips: Yield= 2600 X Square of inches got)*

Please pay/Received Rs.....(Rs 2,000)towards this groundwater investigation/survey.

Place: Bangalore

Date: 3/08/2020

Bhustalimath B M

Groundwater & Water Harvesting Consultant

Mobiles - 9538909542 & 9902498502 OR 7411008937

#95, TF-1, Adishree Aptt, Nr Krishna temple, DBSandra, Vidyaranyapura Po, Bangalore-560097 (India)
Cell: [redacted]9538909542 Resi: [redacted], Mail: bmbmath@gmail.com & [redacted]

9902 498 502

C - Casing

I - Inner
O - outer
S - Slotted

S - Stream M - Motor (Submersible)/Pump

A - Aquifer W - Water level.

P - Pipe (GI/PVC)

Bhustalimath B M (Basavaraj)
B Sc, B Ed, DIRPM, LL B(Spl), CAIIB, MBA

Consultant in Groundwater investigation & Water Harvesting

REPORT ON GROUNDWATER INVESTIGATION/SURVEY

Ref by BBMP Contact Person: K. V. Subba Reddy

Owner: Byatarayanapura Division

Address of the site: 2nd Cross 'A', Nanjappa Layout, Doddabommasandra

Purpose of Survey: Agri/Resi/Domestic/Coml/Indl/Public Utility/Buying & Selling of lands/RE.

Type: Hydrological survey/ second opinion/ Failed or weak Borewell/ Good

Location: (Latitude/longitude): North: ..... East: ..... (N.A)

Soil: Sandy/Loamy/Clayey/ ~~.....~~ Red/ Black/ ~~.....~~

Topography: Clear

Groundwater recharge condition: Excellent/Very good/Moderate/Poor/Very poor/.....

Date of Investigation: Validity: 90 days

Methods adopted: (1)'L' Rods( )(2) Copper wand ( )(3) Coconut ( )(4) Brunton compass( )
(5)'Y' notch ( ) (6) Pendulum/Bob/Chain/Necklace/Wrist watch/Water ball/Mud ball ( )
(7) Geomagnetic flux ( ) (8) Infrasonics ( ) (9) Geobiology( ) (10) Topography/Geomorphology
( ) (11) Vertical Electrical Sounding/Resistivity (VES/VER) ( )(12) Water Detector( )
(13) Water scanner ( ) (14) ..... ( )

Based on above findings/investigations/observations, the following suggestions are made.

Depth to be drilled: About 1100 Mtrs/Ft, Casing Pipe: 250 Mtr/Ft (MS/PVC/Out/In)

Depth to water source/s: About 700 – 1050 Mtr/Ft(stream/aquifer/..)

Approx total yield of water: About ____ Inch dia or About ____ Ltrs/Gal(=4.5 L)per hour.

Diameter of the borewell in inches suggested: 4 ½( ) 6( ) 6 ½( ) 7( ) 7 ½( ) 8( ) 10( )

Special instructions: (a) Align the driller on the streamline; (b) perfect 90 degree drilling.

Brief Map/Identification of Point/s: (Paper-top presumed to be north, right side as east)

N
E



Disclaimer: The above depths and yield are indicative, based on the findings at the time of investigation. There is no guarantee as to depths and discharge of water, as the results are beyond our control. Jurisdiction: Bangalore city. (*Tips: Yield= 2600 X Square of inches got*)

Please pay/Received Rs.....(Rs. 3000)towards this groundwater investigation/survey.

Place: Bangalore

Date: 3/01/2020

Bhustalimath B M
Groundwater & Water Harvesting Consultant

Mobiles - 9538909542 & 9902498502 OR 7411008937

#95, TF-1, Adishree Aptt, Nr Krishna temple, DBSandra, Vidyaranyapura Po, Bangalore-560097 (India)
Cell: ~~9221~~9538909542 Resi: ~~[redacted]~~, Mail: bmbmath@gmail.com & ~~[redacted]~~

9902 498 502

C - Casing
I - Inner
O - outer
S - Slotted

S - Stream
A - Aquifer

M - Motor (Submersible)/Pump
W - Water level.
P - Pipe (GI/PVC)

Bhustalimath B M (Basavaraj)
B Sc, B Ed, DIRPM, LL B(Spl), CAIIB, MBA

Consultant in Groundwater investigation & Water Harvesting

REPORT ON GROUNDWATER INVESTIGATION/SURVEY

Ref by BBMP Contact Person: K.V. Subba Reddy

Owner: Byatarayanapura

Address of the site: 3rd Main, 7th Cross, C. Ramaiah Layout.

Purpose of Survey: Agri/Resi/Domestic/Coml/Indl/Public Utility/Buying & Selling of lands/RE.

Type: Hydrological survey/ second opinion/ Failed or weak Borewell/ Good

Location: (Latitude/longitude): North: ..... East: ..... (N.A)

Soil: Sandy/Loamy/Clayey/ ..... Red/ Black/ ...

Topography: Clear

Groundwater recharge condition: Excellent/Very good/Moderate/Poor/Very poor/.....

Date of Investigation: ..... Validity: 90 days

Methods adopted: (1)'L' Rods( )(2) Copper wand ( )(3) Coconut ( )(4) Brunton compass( )
(5)'Y' notch ( ) (6) Pendulum/Bob/Chain/Necklace/Wrist watch/Water ball/Mud ball ( )
(7) Geomagnetic flux ( ) (8) Infrasonics ( ) (9) Geobiology( ) (10) Topography/Geomorphology
( ) (11) Vertical Electrical Sounding/Resistivity (VES/VER) ( )(12) Water Detector( )
(13) Water scanner ( ) (14) ..... ( )

Based on above findings/investigations/observations, the following suggestions are made.

Depth to be drilled: About 1000 Mtrs/Ft, Casing Pipe: 250 Mtr/Ft (MS/PVC/Out/In)

Depth to water source/s: About 600 - 1000 Mtr/Ft(stream/aquifer/..)

Approx total yield of water: About ..... Inch dia or About ..... Ltrs/Gal(=4.5 L)per hour.

Diameter of the borewell in inches suggested: 4 ½( ) 6( ) 6 ½( ) 7( ) 7 ½( ) 8( ) 10( )

Special instructions: (a) Align the driller on the streamline; (b) perfect 90 degree drilling.

Brief Map/Identification of Point/s: (Paper-top presumed to be north, right side as east)





Disclaimer: The above depths and yield are indicative, based on the findings at the time of investigation. There is no guarantee as to depths and discharge of water, as the results are beyond our control. Jurisdiction: Bangalore city. *(Tips: Yield= 2600 X Square of inches got)*

Please pay/Received Rs.....(Rs. 2,000)towards this groundwater investigation/survey.

Place: Bangalore

Date: 3/05/2020

Bhustalimath B M
Groundwater & Water Harvesting Consultant

Mobiles - 9538909542 & 9902498502 OR 7411008937

#95, TF-1, Adishree Aptt, Nr Krishna temple, DBSandra, Vidyaranyapura Po, Bangalore-560097 (India)
Cell: 9538909542 Resi: [redacted] Mail: bmbmath@gmail.com & [redacted]

9902 498 502

C - Casing
I - Inner
O - outer
S - slotted

S - Stream
A - Aquifer

M - Motor (Submersible)/Pump
W - Water level.
P - Pipe (GI/PVC)